
	Tabriz Petrochemical Company 310 KTPA HDPE Plant							
	Packing, Marking and Shipping Procedure							
	Project	Phase	Unit	Discipline	Type	Serial No.		Rev.
Class: 1	HDPE-16	GM	00	PP	PRC	0001	00	Page 1 of 1

MARKING INSTRUCTION NUMBER AND PLACE OF PRINT (Table NO.1)					Attachment-5		
Mark	CASE or CRATE	NUMBER AND PLACE OF PRINT			BUNDLE	REMARKS	
		SKID or BARE	DRUM	WOODEN DRUM			
Main Shipping Mark	each 1 in front, one side and top panel in case of the crate, marks shall be stenciled to the plywood having the thickness of more than 2.7mm and nailed firmly to the place where bracing members exist.	each 1 at the center of both sides.	2 in side (Package No. shall be stenciled intop)	each 1 in both side	Two or more labels or tags shall be attached according to the style and size of package	1. Abbreviations should have period (.)	
Sling Mark	each 2 in both sides		unnecessary			Extra heavy or long cargo shall have clear and sure marks at the correct places	
Instruction for Handling Mark	Center Mark	each 1 in both sides				Stencil printing is not necessary for the package of about 1 m3 and less than 500 kg in weight.	
	Other Mark	each 1 in both sides and ends for "Top mark", and for other marks are each 1 in both ends.	not necessary	at the upper part of both sides.	in both sides.	unnecessary	Care marks shall be limited to absolutely necessary one.
(Approximate) Weight Mark	1 in top panel	1 in top	unnecessary				1. Hand writing is permissible. 2. To print the weight for more than 3t of package. 3. Unit should be in ton. 4. Size of letter is larger than 15cm.
Shipper's Mark	each 1 in both ends	each 1 at the center of both sides.	each 1 at the under of both sides.		each 1 at the margin of both sides.		
Storage Category Mark	each 1 of Left upper in both ends and 1 of Left upper on top panel	each 1 at the in both sides.	1 of at the upper part	each 1 of Left upper part in both sides.	each 1 at the margin of both sides.		
Reference Drawing No.	No. 1 (Fig-1)	No. 2 (Fig-2)	No. 3 (Fig-4)	No. 3 (Fig-4)	No. 2 (Fig-3)		
Note : In case the stencil is impossible, metal label shall be attached.							