

	<b>Comment Reply Sheet</b>		BUSHEHR PETROCHEMICAL COMPANY		
			Con. No.:		
		Issue Date: 08/Aug/2022	Rev.:02		
	Comment Sheet Ref.No.:		Doc Description: Sub Vendor list		
	Transmittal No.: APCES-V-00174		Doc. No.: BU-20-VD-303-PE-LST-0002		
	Transmittal Date: 08/Aug/2022		Doc Rev.: 02		
Item	CHCE Comment	Vendor Clarification			
1	UCP Local MCC Local Control Panel (LCP) Electrical heater	Repeated answer - UCP >>> added electrical panel EX - Local MCC >>> added electrical panel Safe Area - Local Control Panel (LCP) >> added electrical panel EX - Electrical heater >>> part compressor; manufacturing standard			

**CES Reply:**

- UCP: UCS is different from electrical panel. UCPs manufacturer shall be added to sub-vendor list.
- Local MCC: Local MCC (power distribution panel) is located in ZONE2 IIC T3. Manufacturer of power distribution panel shall be specified in sub-vendor list.
- Local Control Panel : Since local panel is something different from local MCC (power distribution panel), separate row shall be inserted to document.
- Electrical heater : Manual standard is related to standard design. If compressor manufacturer is manufacturer of oil heater, it shall be specified in sub-vendor list.