



Vendor: 	<b>STYRENE PARK OFFSITE</b>  <b>PAINTING INSPECTION REPORT</b>	Owner: 	Report No. : FPA-HX127-RU0001B-E02-PA-001  Date: 4/11/2025  SHEET 1 OF 1
--	--	---	---


Contract No.:	-				P.O.No.:	EI027-FPA-VD-QC-PRO-008												
Project No.:	HX 127			Item No.:	RU0001B-E02				Paint Specification No.:	Project Spec								
Paint Layer	As per Spec:			Humidity (%)	Amb. temp. °C		Surface Temp. °C		Dew Point (°C)	MEK. Test:		Adhesion		Total DFT µm	Measured DFT µm			Manufacture Batch No.
	Paint Type	DFT µm	Ral No.		Min.	Max.	Min.	Max.		Acc.	Rej.	Acc.	Rej.		Min.	Max.	Ave.	
Primer:	Zinc Rich Epoxy	70	-	21%	20	24	20	25	4	-	-	Acc.	-	70	65	80	72	14031222
Intermediate	Epoxy polyamide MIO filled	100	-	20%	18	24	18	20	5	-	-	Acc.	-	170	164	175	169	14031153
Top Coating	Aliphatic Polyurethane	50	7038	24%	16	23	18	24	4	-	-	Acc.	-	225	218	235	226	14031220

JUDGEMENT:      SATISFACTORY            UNSATISFACTORY     

<b>FPA QC.</b>	<b>TPI</b>	<b>OWNER</b>
NAME: DATE: SIGNATURE:	NAME: DATE: SIGNATURE:	NAME: DATE: SIGNATURE:

  
**FAHAMEH**  
 Eng. & Ind. Co.  
 Witnessed   
 Reviewed

  
 FARNIKAN PARK OFFSITE  
 Quality Control  
 Dept.

  
 Sojadian